# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/01/2026 | 23.2 | |
| 2/01/2026 | 14.6 | |
| 3/01/2026 | 8.63 | |
| 4/01/2026 | 8.2 | |
| 5/01/2026 | 8.81 | |
| 6/01/2026 | 11.9 | |
| 7/01/2026 | 16.5 | |
| 8/01/2026 | 15.7 | |
| 9/01/2026 | 14.1 | |
| 10/01/2026 | 15.8 | |
| 11/01/2026 | 31.3 | |
| 12/01/2026 | 25.6 | |
| 13/01/2026 | 101 | Results attributed to non-mining related - offsite dust sources |
| 14/01/2026 | 39.5 | |
| 15/01/2026 | 17.1 | |
| 16/01/2026 | 19.5 | |
| 17/01/2026 | 20.5 | |
| 18/01/2026 | N/A | |
| 19/01/2026 | 7.17 | |
| 20/01/2026 | 12.2 | |
| 21/01/2026 | N/A | |
| 22/01/2026 | 27 | |
| 23/01/2026 | 49.2 | |
| 24/01/2026 | 18.5 | |
| 25/01/2026 | 44.2 | |
| 26/01/2026 | 52.8 | Results attributed to non-mining related - offsite dust sources |
| 27/01/2026 | 40.2 | |
| 28/01/2026 | 30.4 | |
| 29/01/2026 | 35.5 | |
| 30/01/2026 | 30.4 | |
| 31/01/2026 | N/A | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration

N/A – TEOM Power Outage/ comms problem with unit – insufficient data available

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/02/2026 | N/A | |
| 2/02/2026 | 56.9 | Results attributed to non-mining related – offsite dust sources |
| 3/02/2026 | 18.9 | |
| 4/02/2026 | 51 | Results attributed to non-mining related – offsite dust sources |
| 5/02/2026 | 38.1 | |
| 6/02/2026 | 36.5 | |
| 7/02/2026 | 26.4 | |
| 8/02/2026 | 24.2 | |
| 9/02/2026 | 21.9 | |
| 10/02/2026 | 9.94 | |
| 11/02/2026 | 14.8 | |
| 12/02/2026 | 35.4 | |
| 13/02/2026 | 9.48 | |
| 14/02/2026 | 6.91 | |
| 15/02/2026 | 8.8 | |
| 16/02/2026 | 9.97 | |
| 17/02/2026 | 12.6 | |
| 18/02/2026 | 54 | Results attributed to non-mining related – offsite dust sources |
| 19/02/2026 | 26.1 | |
| 20/02/2026 | 21.2 | |
| 21/02/2026 | 13.6 | |
| 22/02/2026 | 13.8 | |
| 23/02/2026 | 19 | |
| 24/02/2026 | 11.9 | |
| 25/02/2026 | 37.9 | |
| 26/02/2026 | 17 | |
| 27/02/2026 | 12.2 | |
| 28/02/2026 | 14.7 | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration

N/A – TEOM Power Outage/ comms problem with unit – insufficient data available

*Note *- Flixton monitor is utilized as an operation*
*management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/03/2026 | 9.51 | |
| 2/03/2026 | 12.2 | |
| 3/03/2026 | 26.2 | |
| 4/03/2026 | 24 | |
| 5/03/2026 | 19.5 | |
| 6/03/2026 | 23.4 | |
| 7/03/2026 | 10.3 | |
| 8/03/2026 | 3.18 | |
| 9/03/2026 | 6.88 | |
| 10/03/2026 | 13.7 | |
| 11/03/2026 | 12.8 | |
| 12/03/2026 | 24.6 | |
| 13/03/2026 | 38.1 | |
| 14/03/2026 | 19.9 | |
| 15/03/2026 | 14.4 | |
| 16/03/2026 | 22.5 | |
| 17/03/2026 | 26.3 | |
| 18/03/2026 | 32.8 | |
| 19/03/2026 | 31.9 | |
| 20/03/2026 | 12.7 | |
| 21/03/2026 | 13.7 | |
| 22/03/2026 | 16.1 | |
| 23/03/2026 | 22.7 | |
| 24/03/2026 | 17.9 | |
| 25/03/2026 | 22.7 | |
| 26/03/2026 | 35.3 | |
| 27/03/2026 | 23 | |
| 28/03/2026 | 12.7 | |
| 29/03/2026 | 12.9 | |
| 30/03/2026 | 15.5 | |
| 31/03/2026 | 17.9 | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/04/2026 | 17.7 | |
| 2/04/2026 | 20 | |
| 3/04/2026 | 25.2 | |
| 4/04/2026 | 19.4 | |
| 5/04/2026 | 12.7 | |
| 6/04/2026 | 17.6 | |
| 7/04/2026 | 29.1 | |
| 8/04/2026 | 43.7 | |
| 9/04/2026 | 37.6 | |
| 10/04/2026 | 45.1 | |
| 11/04/2026 | 40.6 | |
| 12/04/2026 | 20.9 | |
| 13/04/2026 | 26.2 | |
| 14/04/2026 | 29.5 | |
| 15/04/2026 | 38.9 | |
| 16/04/2026 | 33.1 | |
| 17/04/2026 | 34.5 | |
| 18/04/2026 | 32.1 | |
| 19/04/2026 | 36.3 | |
| 20/04/2026 | 40.7 | |
| 21/04/2026 | 38.5 | |
| 22/04/2026 | 24.3 | |
| 23/04/2026 | 7.25 | |
| 24/04/2026 | 13.4 | |
| 25/04/2026 | 27.3 | |
| 26/04/2026 | 25.8 | |
| 27/04/2026 | 31.6 | |
| 28/04/2026 | 36 | |
| 29/04/2026 | 18.9 | |
| 30/04/2026 | S | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/05/2026 | 6.23 | |
| 2/05/2026 | 20.7 | |
| 3/05/2026 | 24.3 | |
| 4/05/2026 | 27 | |
| 5/05/2026 | 15.5 | |
| 6/05/2026 | 7.38 | |
| 7/05/2026 | 11.4 | |
| 8/05/2026 | 12.3 | |
| 9/05/2026 | 12.2 | |
| 10/05/2026 | 15.2 | |
| 11/05/2026 | 22 | |
| 12/05/2026 | 19.8 | |
| 13/05/2026 | 15 | |
| 14/05/2026 | 10.4 | |
| 15/05/2026 | 11.3 | |
| 16/05/2026 | 13.9 | |
| 17/05/2026 | 20.1 | |
| 18/05/2026 | 19.8 | |
| 19/05/2026 | 6.68 | |
| 20/05/2026 | 5.97 | |
| 21/05/2026 | 8.67 | |
| 22/05/2026 | 7.92 | |
| 23/05/2026 | 6.33 | |
| 24/05/2026 | 9.83 | |
| 25/05/2026 | 12.9 | |
| 26/05/2026 | 11 | |
| 27/05/2026 | 8.7 | |
| 28/05/2026 | 6.05 | |
| 29/05/2026 | 5.23 | |
| 30/05/2026 | 5.93 | |
| 31/05/2026 | 7.36 | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/06/2026 | 7.07 | |
| 2/06/2026 | 9.77 | |
| 3/06/2026 | 16.3 | |
| 4/06/2026 | 13.6 | |
| 5/06/2026 | 8.26 | |
| 6/06/2026 | 5.81 | |
| 7/06/2026 | 6.71 | |
| 8/06/2026 | 8.32 | |
| 9/06/2026 | 7.11 | |
| 10/06/2026 | 8.78 | |
| 11/06/2026 | 14.6 | |
| 12/06/2026 | 5.48 | |
| 13/06/2026 | 4.87 | |
| 14/06/2026 | 7.05 | |
| 15/06/2026 | 7.94 | |
| 16/06/2026 | 6.85 | |
| 17/06/2026 | 10.5 | |
| 18/06/2026 | 9.03 | |
| 19/06/2026 | 10.5 | |
| 20/06/2026 | 6.64 | |
| 21/06/2026 | 4.82 | |
| 22/06/2026 | 7.94 | |
| 23/06/2026 | 5.31 | |
| 24/06/2026 | 2.8 | |
| 25/06/2026 | 13.8 | |
| 26/06/2026 | 10.7 | |
| 27/06/2026 | 11.4 | |
| 28/06/2026 | 9.11 | |
| 29/06/2026 | 4.05 | |
| 30/06/2026 | 4.53 | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/07/2026 | 6.93 | |
| 2/07/2026 | 7.73 | |
| 3/067/2026 | 5.42 | |
| 4/07/2026 | 7.16 | |
| 5/07/2026 | 7.76 | |
| 6/07/2026 | 5.52 | |
| 7/07/2026 | 7.68 | |
| 8/07/2026 | 8.82 | |
| 9/07/2026 | 9.4 | |
| 10/07/2026 | 17.7 | |
| 11/07/2026 | 11.6 | |
| 12/07/2026 | 7.3 | |
| 13/07/2026 | 14 | |
| 14/07/2026 | 16.9 | |
| 15/07/2026 | N/A | power interruption |
| 16/07/2026 | N/A | power interruption |
| 17/07/2026 | 10.8 | |
| 18/07/2026 | 9.99 | |
| 19/07/2026 | 11.2 | |
| 20/07/2026 | 23 | |
| 21/07/2026 | 13.7 | |
| 22/07/2026 | 14.1 | |
| 23/07/2026 | 18.4 | |
| 24/07/2026 | N/A | power interruption |
| 25/07/2026 | 11.3 | |
| 26/07/2026 | 16.4 | |
| 27/07/2026 | 16.6 | |
| 28/06/2026 | 25.5 | |
| 29/07/2026 | 17.5 | |
| 30/07/2026 | 20.4 | |
| 31/07/2026 | 38.5 | |

S -- Servicing / calibration

N/A – TEOM Power Outage/comms problem with unit – insufficient data available

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/08/2026 | 27.3 | |
| 2/08/2026 | 14.8 | |
| 3/08/2026 | 30.1 | |
| 4/08/2026 | 8.37 | |
| 5/08/2026 | 20.5 | |
| 6/08/2026 | 15.7 | |
| 7/08/2026 | 22.9 | |
| 8/08/2026 | 17.4 | |
| 9/08/2026 | 17.7 | |
| 10/08/2026 | N/A | Power interruption |
| 11/08/2026 | 10.5 | |
| 12/08/2026 | 17.4 | |
| 13/08/2026 | 17.2 | |
| 14/08/2026 | 12.4 | |
| 15/08/2026 | 16.5 | |
| 16/08/2026 | 10.6 | |
| 17/08/2026 | 7.7 | |
| 18/08/2026 | 12.5 | |
| 19/08/2026 | 14.1 | |
| 20/08/2026 | 18.9 | |
| 21/08/2026 | 24.3 | |
| 22/08/2026 | 4.41 | |
| 23/08/2026 | 6.55 | |
| 24/08/2026 | 8.64 | |
| 25/08/2026 | 12 | |
| 26/08/2026 | 7.54 | |
| 27/08/2026 | 8.31 | |
| 28/08/2026 | 8.95 | |
| 29/08/2026 | 18.1 | |
| 30/08/2026 | 13.2 | |
| 31/08/2026 | 20.6 | |

S -- Servicing / calibration

N/A – TEOM Power Outage/comms problem with unit – insufficient data available

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

# BTM Air Quality Management Strategy
# Tarrawonga Coal Mine
# Dust Monitoring

| Date | Flixton* $PM_{10}$ 24hr Average [µg/$m^3$] | Operational Response |
|---|---|---|
| 1/09/2026 | 20.5 | |
| 2/09/2026 | 28.6 | |
| 3/09/2026 | 29.9 | |
| 4/09/2026 | 12.6 | |
| 5/09/2026 | 26.3 | |
| 6/09/2026 | 16.8 | |
| 7/09/2026 | 15.3 | |
| 8/09/2026 | 17.5 | |
| 9/09/2026 | 20.9 | |
| 10/09/2026 | 19.2 | |
| 11/09/2026 | 18.8 | |
| 12/09/2026 | 12.1 | |
| 13/09/2026 | 15.8 | |
| 14/09/2026 | 22.8 | |
| 15/09/2026 | 23.9 | |
| 16/09/2026 | 16.9 | |
| 17/09/2026 | 16.2 | |
| 18/09/2026 | 17.6 | |
| 19/09/2026 | 20.8 | |
| 20/09/2026 | 18.2 | |
| 21/09/2026 | 35.3 | |
| 22/09/2026 | N/A | Damage to power supply |
| 23/09/2026 | 31 | |
| 24/09/2026 | 28.7 | |
| 25/09/2026 | 24.9 | |
| 26/09/2026 | 26.5 | |
| 27/09/2026 | 25.5 | |
| 28/09/2026 | 14.3 | |
| 29/09/2026 | 26.9 | |
| 30/09/2026 | 25.3 | |

S -- Servicing / calibration

N/A – TEOM Power Outage/comms problem with unit – insufficient data available

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Whitehaven

**Tarrawonga Coal Mine**

## AQMS Monthly Monitoring Reports
# Correction Log

| Month of AQMS Report | Original Month of Publishing | Month of Correction | Month of Republishing | Correction/s Made |
|---|---|---|---|---|
| January 2026 | February 2026 | September 2026 | September 2026 | • Dust PM10 values changed to reflect correct 24hr data for the Flixton property TEOM. |
| February 2026 | March 2026 | September 2026 | September 2026 | • Dust PM10 values changed to reflect correct 24hr data for the Flixton property TEOM.<br>• Addition of comments for any PM10 value >50 µg/$m^3$ |