BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring

Date	Flixton* PM$_{10}$ 24hr Average [μg/m^3]	Operational Response
01-05-23	4.5 (C)	No action required
02-05-23	9.5	No action required
03-05-23	10.1	No action required
04-05-23	16.5	No action required
05-05-23	19.9	No action required
06-05-23	16.9	No action required
07-05-23	10.2	No Mining Activities
08-05-23	11	No action required
09-05-23	11.4	No action required
10-05-23	21.8	No action required
11-05-23	27.5	No action required
12-05-23	19.4	No action required
13-05-23	22	No action required
14-05-23	21.5	No Mining Activities
15-05-23	16.4	No action required
16-05-23	28.6 (C)	No action required
17-05-23	12.9	No action required
18-05-23	11.2	No action required
19-05-23	18.4	No action required
20-05-23	16	No action required
21-05-23	13.6	No Mining Activities
22-05-23	9.4	No action required
23-05-23	14.3	No action required
24-05-23	19	No action required
25-05-23	30.8	No action required
26-05-23	22.9	No action required
27-05-23	11.4	No action required
28-05-23	9.3	No Mining Activities
29-05-23	16.8	No action required
30-05-23	15.8	No action required
31-05-23	14.3	No action required

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall or work on the area.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy Therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.