

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/10/2018	16.2	9.4	No action required
2/10/2018	16.4	9.9	No action required
3/10/2018	19.0	7.5	No action required
4/10/2018	12.3	8.2	No action required
5/10/2018	5.6	4.4	No action required
6/10/2018	6.8	6.4	No action required
7/10/2018	8.6	6.9	No action required
8/10/2018	9.7	6.8	No action required
9/10/2018	12.7	13.7	No action required
10/10/2018	N/A	10.5	No action required - Maintenance undertaken at TEOM 1
11/10/2018	N/A	N/A	No action required - Maintenance undertaken at TEOM units
12/10/2018	1.9	6.2	No action required
13/10/2018	1.6	6.0	No action required
14/10/2018	3.3	4.8	No action required
15/10/2018	4.0	9.0	No action required
16/10/2018	3.9	3.2	No action required
17/10/2018	3.2	4.4	No action required
18/10/2018	6.8	8.2	No action required
19/10/2018	9.2	10.9	No action required
20/10/2018	12.0	14.0	No action required
21/10/2018	6.7	N/A	No action required - Maintenance undertaken at TEOM 2
22/10/2018	9.3	10.6	No action required
23/10/2018	9.9	9.9	No action required
24/10/2018	11.4	13.2	No action required
25/10/2018	14.7	18.9	No action required
26/10/2018	17.2	22.3	No action required
27/10/2018	20.1	19.7	No action required
28/10/2018	19.9	30.5	No action required
29/10/2018	14.5	15.0	No action required
30/10/2018	15.0	19.7	No action required
31/10/2018	18.2	20.5	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

N/A - not available