

BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring

| Date | Flixton* PM ₁₀ 24hr Average [µg/m ³] | Operational Response |
|------------|---|---|
| 1/01/2026 | 26 | |
| 2/01/2026 | 17 | |
| 3/01/2026 | 9 | |
| 4/01/2026 | 12 | |
| 5/01/2026 | 13 | |
| 6/01/2026 | 12 | |
| 7/01/2026 | 20 | |
| 8/01/2026 | 20 | |
| 9/01/2026 | 20 | |
| 10/01/2026 | 15 | |
| 11/01/2026 | 35 | |
| 12/01/2026 | 26 | |
| 13/01/2026 | 103 | Results attributed to non-mining related - offsite dust sources |
| 14/01/2026 | 42 | |
| 15/01/2026 | 20 | |
| 16/01/2026 | 23 | |
| 17/01/2026 | 21 | |
| 18/01/2026 | 11 | |
| 19/01/2026 | 8 | |
| 20/01/2026 | 14 | |
| 21/01/2026 | 31 | |
| 22/01/2026 | 27 | |
| 23/01/2026 | 49 | |
| 24/01/2026 | 18 | |
| 25/01/2026 | 44 | |
| 26/01/2026 | 53 | Results attributed to non-mining related - offsite dust sources |
| 27/01/2026 | 41 | |
| 28/01/2026 | 31 | |
| 29/01/2026 | 36 | |
| 30/01/2026 | 31 | |
| 31/01/2026 | 48 | |

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*