

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [µg/m ³]	Operational Response
1/05/2025	6.97	No action required – Continue to monitor
2/05/2025	6.9	No action required – Continue to monitor
3/05/2025	8.38	No action required – Continue to monitor
4/05/2025	8.76	No action required – Continue to monitor
5/05/2025	6.37	No action required – Continue to monitor
6/05/2025	5.92	No action required – Continue to monitor
7/05/2025	10.4	No action required – Continue to monitor
8/05/2025	0 (S)	No action required – Continue to monitor
9/05/2025	10.4	No action required – Continue to monitor
10/05/2025	6.5	No action required – Continue to monitor
11/05/2025	0 (S)	No action required – Continue to monitor
12/05/2025	9.34	No action required – Continue to monitor
13/05/2025	9.17	No action required – Continue to monitor
14/05/2025	9.76	No action required – Continue to monitor
15/05/2025	5.68	No action required – Continue to monitor
16/05/2025	5.84	No action required – Continue to monitor
17/05/2025	7.36	No action required – Continue to monitor
18/05/2025	10.9	No action required – Continue to monitor
19/05/2025	5.66	No action required – Continue to monitor
20/05/2025	4.74	No action required – Continue to monitor
21/05/2025	4.16	No action required – Continue to monitor
22/05/2025	4.76	No action required – Continue to monitor
23/05/2025	7.86	No action required – Continue to monitor
24/05/2025	9.17	No action required – Continue to monitor
25/05/2025	9.74	No action required – Continue to monitor
26/05/2025	11.7	No action required – Continue to monitor
27/05/2025	49.7	No action required – Continue to monitor
28/05/2025	9.06	No action required – Continue to monitor
29/05/2025	7.36	No action required – Continue to monitor
30/05/2025	8.34	No action required – Continue to monitor
31/05/2025	8.54	No action required – Continue to monitor

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*