

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/05/2020	5.2	No action required
2/05/2020	11.0	No action required
3/05/2020	4.4	No Mining Activity
4/05/2020	8.7	No action required
5/05/2020	11.9	No action required
6/05/2020	16.6	No action required
7/05/2020	13.2	No action required
8/05/2020	18.0	No action required
9/05/2020	17.4	No action required
10/05/2020	13.1	No Mining Activity
11/05/2020	10.5	No action required
12/05/2020	9.4	No action required
13/05/2020	19.7	No action required
14/05/2020	15.0	No action required
15/05/2020	17.0	No action required
16/05/2020	10.8	No action required
17/05/2020	9.3	No Mining Activity
18/05/2020	16.3	No action required
19/05/2020	7.1	No action required
20/05/2020	18.7	No action required
21/05/2020	3.8	No action required
22/05/2020	6.4	No action required
23/05/2020	10.0	No action required
24/05/2020	10.2	No Mining Activity
25/05/2020	7.0	No action required
26/05/2020	7.1	No action required
27/05/2020	6.7	No action required
28/05/2020	9.2	No action required
29/05/2020	10.8	No action required
30/05/2020	8.3	No action required
31/05/2020	14.2	No Mining Activity

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.