

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/06/2020	16.7	No action required
2/06/2020	8.5	No action required
3/06/2020	7.0	No action required
4/06/2020	12.0	No action required
5/06/2020	8.8	No action required
6/06/2020	11.9	No action required
7/06/2020	14.3	No Mining Activity
8/06/2020	12.7	No action required
9/06/2020	12.0	No action required
10/06/2020	9.4	No action required
11/06/2020	4.8	No action required
12/06/2020	11.2	No action required
13/06/2020	10.5	No action required
14/06/2020	6.8	No Mining Activity
15/06/2020	4.1	No action required
16/06/2020	7.1	No action required
17/06/2020	7.2	No action required
18/06/2020	8.0	No action required
19/06/2020	4.2	No action required
20/06/2020	8.7	No action required
21/06/2020	6.4	No Mining Activity
22/06/2020	6.0	No action required
23/06/2020	8.0	No action required
24/06/2020	2.6	No action required
25/06/2020	4.6	No action required
26/06/2020	3.9	No action required
27/06/2020	7.1	No action required
28/06/2020	9.4	No Mining Activity
29/06/2020	8.6	No action required
30/06/2020	9.8	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*