

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/07/2020	14.1	No action required
2/07/2020	16.7	No action required
3/07/2020	11.4	No action required
4/07/2020	8.5	No action required
5/07/2020	5.9	No Mining Activity
6/07/2020	6.2	No action required
7/07/2020	11.8	No action required
8/07/2020	11.7	No action required
9/07/2020	13.4	No action required
10/07/2020	8.8	No action required
11/07/2020	6.9	No action required
12/07/2020	8.4	No Mining Activity
13/07/2020	4.6	No action required
14/07/2020	7.3	No action required
15/07/2020	5.3	No action required
16/07/2020	6.3	No action required
17/07/2020	7.9	No action required
18/07/2020	5.1	No action required
19/07/2020	13.2	No Mining Activity
20/07/2020	8.5	No action required
21/07/2020	9.2	No action required
22/07/2020	19.2	No action required
23/07/2020	16.3	No action required
24/07/2020	15.0	No action required
25/07/2020	4.4	No action required
26/07/2020	3.7	No Mining Activity
27/07/2020	6.1	No action required
28/07/2020	7.1	No action required
29/07/2020	5.3	No action required
30/07/2020	7.4	No action required
31/07/2020	9.9	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*