

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/09/2020	16.4	No action required
2/09/2020	29.7	No action required
3/09/2020	28.1	No action required
4/09/2020	28.3	No action required
5/09/2020	14.0	No action required
6/09/2020	15.5	No Mining Activities
7/09/2020	15.0	No action required
8/09/2020	14.2	No action required
9/09/2020	23.4	No action required
10/09/2020	3.9	No action required
11/09/2020	7.4	No action required
12/09/2020	6.5	No action required
13/09/2020	9.5	No Mining Activities
14/09/2020	13.8	No action required
15/09/2020	13.6	No action required
16/09/2020	16.4	No action required
17/09/2020	16.5	No action required
18/09/2020	17.9	No action required
19/09/2020	12.0	No action required
20/09/2020	9.2	No Mining Activities
21/09/2020	17.2	No action required
22/09/2020	19.9	No action required
23/09/2020	19.8	No action required
24/09/2020	15.2	No action required
25/09/2020	41.4	No action required
26/09/2020	8.8	No action required
27/09/2020	7.8	No Mining Activities
28/09/2020	12.3	No action required
29/09/2020	16.3	No action required
30/09/2020	13.6	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*