

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/10/2020	10.7	No action required
2/10/2020	10.5	No action required
3/10/2020	20.4	No action required
4/10/2020	16.8	No Mining Activities
5/10/2020	17.7	No action required
6/10/2020	20.8	No action required
7/10/2020	24.7	No action required
8/10/2020	28.6	No action required
9/10/2020	10.7	No action required
10/10/2020	10.3	No action required
11/10/2020	11.2	No Mining Activities
12/10/2020	17.8	No action required
13/10/2020	9.6	No action required
14/10/2020	14.0	No action required
15/10/2020	18.0	No action required
16/10/2020	19.8	No action required
17/10/2020	25.9	No action required
18/10/2020	12.7	No Mining Activities
19/10/2020	11.4	No action required
20/10/2020	8.7	No action required
21/10/2020	15.8	No action required
22/10/2020	S	Power outage at monitor due to rain
23/10/2020	12.6	No action required
24/10/2020	7.7	No action required
25/10/2020	13.9	No Mining Activities
26/10/2020	9.9	No action required
27/10/2020	10.0	No action required
28/10/2020	7.9	No action required
29/10/2020	11.0	No action required
30/10/2020	16.2	No action required
31/10/2020	45.0	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*