

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
01/11/2020	13.3	No Mining Activities
02/11/2020	12.2	No action required
03/11/2020	13.7	No action required
04/11/2020	26.2	No action required
05/11/2020	30.2	No action required
06/11/2020	12.8	No action required
07/11/2020	19	No action required
08/11/2020	17.1	No Mining Activities
09/11/2020	20.4	No action required
10/11/2020	36.6	No action required
11/11/2020	27.5	No action required
12/11/2020	S	Power outage at monitor
13/11/2020	25.8	No action required
14/11/2020	16.5 (C)	No action required
15/11/2020	17.1	No Mining Activities
16/11/2020	34.9	No action required
17/11/2020	28.1	No action required
18/11/2020	19.0	No action required
19/11/2020	25.6	No action required
20/11/2020	36.3	No action required
21/11/2020	22.9	No action required
22/11/2020	21.8	No Mining Activities
23/11/2020	41.1	No action required
24/11/2020	11.6	No action required
25/11/2020	15.3 (C)	No action required
26/11/2020	21.7	No action required
27/11/2020	16.9	No action required
28/11/2020	21.1	No action required
29/11/2020	43.0	No Mining Activities
30/11/2020	30.8 (C)	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*