

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/12/2020	39.1	No action required
2/12/2020	48.8	No action required
3/12/2020	N/A	No action required
4/12/2020	N/A	No action required
5/12/2020	13.8	No action required
6/12/2020	19.6	No Mining Activities
7/12/2020	23.2	No action required
8/12/2020	10.5	No action required
9/12/2020	17.1	No action required
10/12/2020	32.9	No action required
11/12/2020	10.7	No action required
12/12/2020	10.6	No action required
13/12/2020	8.9	No Mining Activities
14/12/2020	7.0	No action required
15/12/2020	9.7	No action required
16/12/2020	8.7	No action required
17/12/2020	7.4	No action required
18/12/2020	12.4 (C)	No action required
19/12/2020	10.5	No action required
20/12/2020	11.5 (C)	No Mining Activities
21/12/2020	8.3	No action required
22/12/2020	4.4 (C)	No action required
23/12/2020	7.2	No action required
24/12/2020	13.3	No action required
25/12/2020	9.9 (C)	No Mining Activities
26/12/2020	9.0 (C)	No Mining Activities
27/12/2020	14.1 (C)	No Mining Activities
28/12/2020	9.0 (C)	No Mining Activities
29/12/2020	7.3 (C)	No action required
30/12/2020	N/A	No action required
31/12/2020	6.7	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*