

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
01/01/2021	5.4	No action required
02/01/2021	5.8(C)	No action required
03/01/2021	5.0	No Mining Activities
04/01/2021	7.2	No action required
05/01/2021	9.6	No action required
06/01/2021	9.7	No action required
07/01/2021	7.2	No action required
08/01/2021	8.5(C)	No action required
09/01/2021	8.2	No action required
10/01/2021	7.3	No Mining Activities
11/01/2021	13.7	No action required
12/01/2021	9.2(C)	No action required
13/01/2021	6.5(C)	No action required
14/01/2021	13.5	No action required
15/01/2021	9.7	No action required
16/01/2021	12.4(C)	No action required
17/01/2021	12.4(C)	No Mining Activities
18/01/2021	12.0	No action required
19/01/2021	10.5	No action required
20/01/2021	10.1	No action required
21/01/2021	14.0	No action required
22/01/2021	19.9	No action required
23/01/2021	16.7	No action required
24/01/2021	15.9	No Mining Activities
25/01/2021	26.3	No action required
26/01/2021	20.4	No action required
27/01/2021	29.4	No action required
28/01/2021	16.5	No action required
29/01/2021	17.9	No action required
30/01/2021	12.7	No action required
31/01/2021	18.0	No Mining Activities

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*