

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/02/2021	20.6	No action required
2/02/2021	7.4	No action required
3/02/2021	14.4	No action required
4/02/2021	22.9	No action required
5/02/2021	15.8	No action required
6/02/2021	12.6	No action required
7/02/2021	9.1	No Mining Activities
8/02/2021	15.2	No action required
9/02/2021	14.2	No action required
10/02/2021	15.1	No action required
11/02/2021	10.7	No action required
12/02/2021	17.2 (C)	No action required
13/02/2021	11.4	No action required
14/02/2021	10.9	No Mining Activities
15/02/2021	15.3	No action required
16/02/2021	9.0	No action required
17/02/2021	9.5 (C)	No action required
18/02/2021	9.6	No action required
19/02/2021	9.7	No action required
20/02/2021	6.9	No action required
21/02/2021	8.1	No Mining Activities
22/02/2021	15.5	No action required
23/02/2021	23.1	No action required
24/02/2021	12.5	No action required
25/02/2021	5.4	No action required
26/02/2021	11.9	No action required
27/02/2021	7.1	No action required
28/02/2021	8.8 (C)	No Mining Activities

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.