

**BTM Air Quality Management Strategy  
Tarrawonga Coal Mine  
Dust Monitoring**

Date	Flixton* PM <sub>10</sub> 24hr Average [ $\mu\text{g}/\text{m}^3$ ]	Operational Response
1/05/2021	10.4	No action required
2/05/2021	12.9	No Mining Activities
3/05/2021	16.2	No action required
4/05/2021	11.9	No action required
5/05/2021	5.9	No action required
6/05/2021	7.7	No action required
7/05/2021	6.8	No action required
8/05/2021	10.4	No action required
9/05/2021	3.9 (C)	No Mining Activities
10/05/2021	8.43	No action required
11/05/2021	10.6 (C)	No action required
12/05/2021	11.6	No action required
13/05/2021	10.3	No action required
14/05/2021	11.3	No action required
15/05/2021	9.6	No action required
16/05/2021	9.8	No Mining Activities
17/05/2021	11.3	No action required
18/05/2021	11.8	No action required
19/05/2021	16.1 (C)	No action required
20/05/2021	14.8	No action required
21/05/2021	17.5	No action required
22/05/2021	14.2	No action required
23/05/2021	14.2	No Mining Activities
24/05/2021	15.7	No action required
25/05/2021	10.1	No action required
26/05/2021	16.0 (C)	No action required
27/05/2021	16.4	No action required
28/05/2021	13.2	No action required
29/05/2021	13.6	No action required
30/05/2021	9.7	No Mining Activities
31/05/2021	12.5	No action required

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note \*- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*