

**BTM Air Quality Management Strategy  
Tarrawonga Coal Mine  
Dust Monitoring**

Date	Flixton* PM <sub>10</sub> 24hr Average [ $\mu\text{g}/\text{m}^3$ ]	Operational Response
1/06/2021	17.1 (C)	No action required
2/06/2021	14.6 (C)	No action required
3/06/2021	8.7	No action required
4/06/2021	5.5	No action required
5/06/2021	5.5	No action required
6/06/2021	5.9 (C)	No Mining Activities
7/06/2021	10.2	No action required
8/06/2021	9.8	No action required
9/06/2021	5.2	No action required
10/06/2021	5.7	No action required
11/06/2021	4.7	No action required
12/06/2021	5.7	No action required
13/06/2021	5.4	No Mining Activities
14/06/2021	4.6	No action required
15/06/2021	5.7	No action required
16/06/2021	8.0	No action required
17/06/2021	12.4	No action required
18/06/2021	9.1	No action required
19/06/2021	5.5	No action required
20/06/2021	6.7	No Mining Activities
21/06/2021	6.8	No action required
22/06/2021	6.4	No action required
23/06/2021	6.8	No action required
24/06/2021	6.9	No action required
25/06/2021	6.5	No action required
26/06/2021	5.2	No action required
27/06/2021	4.8	No Mining Activities
28/06/2021	7.6	No action required
29/06/2021	8.0	No action required
30/06/2021	8.0	No action required

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note \*- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*