

**BTM Air Quality Management Strategy  
Tarrawonga Coal Mine  
Dust Monitoring**

Date	Flixton* PM <sub>10</sub> 24hr Average [ $\mu\text{g}/\text{m}^3$ ]	Operational Response
1/06/2022	8.1	No action required
2/06/2022	7.2	No action required
3/06/2022	6.9	No action required
4/06/2022	4.9	No action required
5/06/2022	4.8	No Mining Activities
6/06/2022	8.1	No action required
7/06/2022	10.4	No action required
8/06/2022	7.2	No action required
9/06/2022	7.2	No action required
10/06/2022	7	No action required
11/06/2022	4	No action required
12/06/2022	11.5	No Mining Activities
13/06/2022	6.8	No action required
14/06/2022	11.1	No action required
15/06/2022	13	No action required
16/06/2022	20.7	No action required
17/06/2022	10.9	No action required
18/06/2022	8.2	No action required
19/06/2022	9.8	No Mining Activities
20/06/2022	15	No action required
21/06/2022	13.4	No action required
22/06/2022	12.5	No action required
23/06/2022	10.9	No action required
24/06/2022	11.5	No action required
25/06/2022	8.7	No action required
26/06/2022	27	No Mining Activities
27/06/2022	12.3	No action required
28/06/2022	14.3	No action required
29/06/2022	11.7	No action required
30/06/2022	26.4	No action required

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note \** - Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.

*Note 2:* Data from the 1<sup>st</sup> to the 20<sup>th</sup> of December 2021 was downloaded from the TEOM after repairs to communications were completed.