

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/01/2024	8.8 (C)	No action required – Continue to monitor
2/01/2024	7.7	No action required – Continue to monitor
3/01/2024	15.7	No action required – Continue to monitor
4/01/2024	20.5	No action required – Continue to monitor
5/01/2024	12.0	No action required – Continue to monitor
6/01/2024	10.2	No action required – Continue to monitor
7/01/2024	10.8	No action required – Continue to monitor
8/01/2024	13.6	No action required – Continue to monitor
9/01/2024	11.1	No action required – Continue to monitor
10/01/2024	16.8 (C)	No action required – Continue to monitor
11/01/2024	12.0 (C)	No action required – Continue to monitor
12/01/2024	9.3 (C)	No action required – Continue to monitor
13/01/2024	12.8	No action required – Continue to monitor
14/01/2024	19.8 (C)	No action required – Continue to monitor
15/01/2024	14.6	No action required – Continue to monitor
16/01/2024	12.2 (C)	No action required – Continue to monitor
17/01/2024	5.07	No action required – Continue to monitor
18/01/2024	8.8	No action required – Continue to monitor
19/01/2024	9.9	No action required – Continue to monitor
20/01/2024	15.4	No action required – Continue to monitor
21/01/2024	15.7	No action required – Continue to monitor
22/01/2024	30.9	No action required – Continue to monitor
23/01/2024	15.1	No action required – Continue to monitor
24/01/2024	16.8	No action required – Continue to monitor
25/01/2024	36.5	No action required – Continue to monitor
26/01/2024	28.1 (C)	No action required – Continue to monitor
27/01/2024	37.6	No action required – Continue to monitor
28/01/2024	27.4	No action required – Continue to monitor
29/01/2024	11.7 (C)	No action required – Continue to monitor
30/01/2024	20.1	No action required – Continue to monitor
31/01/2024	21.5	No action required – Continue to monitor

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/02/2024	26.5 (c)	No action required – Continue to monitor
2/02/2024	31.7 (C)	No action required – Continue to monitor
3/02/2024	35.9 (C)	No action required – Continue to monitor
4/02/2024	26.7 (C)	No action required – Continue to monitor
5/02/2024	18.9	No action required – Continue to monitor
6/02/2024	18.7 (C)	No action required – Continue to monitor
7/02/2024	9.5 (C)	No action required – Continue to monitor
8/02/2024	8.8	No action required – Continue to monitor
9/02/2024	16.8	No action required – Continue to monitor
10/02/2024	25.4 (C)	No action required – Continue to monitor
11/02/2024	10.4	No action required – Continue to monitor
12/02/2024	9.0 (C)	No action required – Continue to monitor
13/02/2024	17.0	No action required – Continue to monitor
14/02/2024	48.5 (C)	No action required – Continue to monitor
15/02/2024	20.0	No action required – Continue to monitor
16/02/2024	10.2 (C)	No action required – Continue to monitor
17/02/2024	8.6	No action required – Continue to monitor
18/02/2024	13.9	No action required – Continue to monitor
19/02/2024	14.2	No action required – Continue to monitor
20/02/2024	9.2 (C)	No action required – Continue to monitor
21/02/2024	17.4 (C)	No action required – Continue to monitor
22/02/2024	33.1 (C)	No action required – Continue to monitor
23/02/2024	23.4 (C)	No action required – Continue to monitor
24/02/2024	14.9 (C)	No action required – Continue to monitor
25/02/2024	S	No action required – Continue to monitor
26/02/2024	13.7 (C)	No action required – Continue to monitor
27/02/2024	17.0	No action required – Continue to monitor
28/02/2024	22.0	No action required – Continue to monitor
29/02/2024	22.7	No action required – Continue to monitor

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/03/2024	24.4	No action required – Continue to monitor
2/03/2024	20.2	No action required – Continue to monitor
3/03/2024	14.7	No action required – Continue to monitor
4/03/2024	4.39	No action required – Continue to monitor
5/03/2024	16.6	No action required – Continue to monitor
6/03/2024	13.6	No action required – Continue to monitor
7/03/2024	15.3	No action required – Continue to monitor
8/03/2024	19.4	No action required – Continue to monitor
9/03/2024	17.7	No action required – Continue to monitor
10/03/2024	12.1	No action required – Continue to monitor
11/03/2024	11.1	No action required – Continue to monitor
12/03/2024	13.7	No action required – Continue to monitor
13/03/2024	15.2	No action required – Continue to monitor
14/03/2024	21.2	No action required – Continue to monitor
15/03/2024	27.4	No action required – Continue to monitor
16/03/2024	31.1	No action required – Continue to monitor
17/03/2024	24.3	No action required – Continue to monitor
18/03/2024	16.4	No action required – Continue to monitor
19/03/2024	9.82	No action required – Continue to monitor
20/03/2024	2.62	No action required – Continue to monitor
21/03/2024	11.3	No action required – Continue to monitor
22/03/2024	9.44	No action required – Continue to monitor
23/03/2024	10.3	No action required – Continue to monitor
24/03/2024	12.2	No action required – Continue to monitor
25/03/2024	12.9	No action required – Continue to monitor
26/03/2024	10.4	No action required – Continue to monitor
27/03/2024	15.6	No action required – Continue to monitor
28/03/2024	15.6	No action required – Continue to monitor
29/03/2024	12.8	No action required – Continue to monitor
30/03/2024	14.5	No action required – Continue to monitor
31/03/2024	13.5	No action required – Continue to monitor

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/04/2024	12.2	No action required – Continue to monitor
2/04/2024	15.6	No action required – Continue to monitor
3/04/2024	8.2	No action required – Continue to monitor
4/04/2024	13.4	No action required – Continue to monitor
5/04/2024	4.9	No action required – Continue to monitor
6/04/2024	6.8	No action required – Continue to monitor
7/04/2024	8.0	No action required – Continue to monitor
8/04/2024	10.3	No action required – Continue to monitor
9/04/2024	12.1	No action required – Continue to monitor
10/04/2024	13.4	No action required – Continue to monitor
11/04/2024	16.8	No action required – Continue to monitor
12/04/2024	14.9	No action required – Continue to monitor
13/04/2024	18.7	No action required – Continue to monitor
14/04/2024	15.5	No action required – Continue to monitor
15/04/2024	23.1	No action required – Continue to monitor
16/04/2024	9.5	No action required – Continue to monitor
17/04/2024	9.4	No action required – Continue to monitor
18/04/2024	8.5	No action required – Continue to monitor
19/04/2024	N/A	No action required – Continue to monitor
20/04/2024	N/A	No action required – Continue to monitor
21/04/2024	N/A	No action required – Continue to monitor
22/04/2024	N/A	No action required – Continue to monitor
23/04/2024	N/A	No action required – Continue to monitor
24/04/2024	N/A	No action required – Continue to monitor
25/04/2024	16.0	No action required – Continue to monitor
26/04/2024	23.9	No action required – Continue to monitor
27/04/2024	19.0	No action required – Continue to monitor
28/04/2024	15.4	No action required – Continue to monitor
29/04/2024	12.5	No action required – Continue to monitor
30/04/2024	16.1	No action required – Continue to monitor

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage

*Note * - Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/05/2024	6.0 (C)	No Action Required – Continue Monitoring
2/05/2024	5.4	No Action Required – Continue Monitoring
3/05/2024	7.5	No Action Required – Continue Monitoring
4/05/2024	6.1	No Action Required – Continue Monitoring
5/05/2024	5.3	No Action Required – Continue Monitoring
6/05/2024	6.2	No Action Required – Continue Monitoring
7/05/2024	8.7	No Action Required – Continue Monitoring
8/05/2024	8.1	No Action Required – Continue Monitoring
9/05/2024	7.0	No Action Required – Continue Monitoring
10/05/2024	6.5	No Action Required – Continue Monitoring
11/05/2024	5.9	No Action Required – Continue Monitoring
12/05/2024	4.9	No Action Required – Continue Monitoring
13/05/2024	7.2	No Action Required – Continue Monitoring
14/05/2024	8.3	No Action Required – Continue Monitoring
15/05/2024	10.0	No Action Required – Continue Monitoring
16/05/2024	11.6	No Action Required – Continue Monitoring
17/05/2024	20	No Action Required – Continue Monitoring
18/05/2024	15.9	No Action Required – Continue Monitoring
19/05/2024	7.6	No Action Required – Continue Monitoring
20/05/2024	14.9	No Action Required – Continue Monitoring
21/05/2024	8.0	No Action Required – Continue Monitoring
22/05/2024	8.9	No Action Required – Continue Monitoring
23/05/2024	19.8	No Action Required – Continue Monitoring
24/05/2024	17.3	No Action Required – Continue Monitoring
25/05/2024	13.4	No Action Required – Continue Monitoring
26/05/2024	11.9	No Action Required – Continue Monitoring
27/05/2024	16.8	No Action Required – Continue Monitoring
28/05/2024	17.6	No Action Required – Continue Monitoring
29/05/2024	16.2	No Action Required – Continue Monitoring
30/05/2024	16.3	No Action Required – Continue Monitoring
31/05/2024	18.0	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/06/2024	11.3	No Action Required – Continue Monitoring
2/06/2024	4.43	No Action Required – Continue Monitoring
3/06/2024	3.36	No Action Required – Continue Monitoring
4/06/2024	6.61	No Action Required – Continue Monitoring
5/06/2024	10.6	No Action Required – Continue Monitoring
6/06/2024	6.83	No Action Required – Continue Monitoring
7/06/2024	8.76	No Action Required – Continue Monitoring
8/06/2024	7.8	No Action Required – Continue Monitoring
9/06/2024	8.17	No Action Required – Continue Monitoring
10/06/2024	8.6	No Action Required – Continue Monitoring
11/06/2024	7.32	No Action Required – Continue Monitoring
12/06/2024	11.9	No Action Required – Continue Monitoring
13/06/2024	3.62	No Action Required – Continue Monitoring
14/06/2024	5.69	No Action Required – Continue Monitoring
15/06/2024	10.4	No Action Required – Continue Monitoring
16/06/2024	5.28	No Action Required – Continue Monitoring
17/06/2024	6.25	No Action Required – Continue Monitoring
18/06/2024	8.19	No Action Required – Continue Monitoring
19/06/2024	9.08	No Action Required – Continue Monitoring
20/06/2024	6.03	No Action Required – Continue Monitoring
21/06/2024	2.20	No Action Required – Continue Monitoring
22/06/2024	9.1	No Action Required – Continue Monitoring
23/06/2024	8.89	No Action Required – Continue Monitoring
24/06/2024	8.35	No Action Required – Continue Monitoring
25/06/2024	10.6	No Action Required – Continue Monitoring
26/06/2024	16.7	No Action Required – Continue Monitoring
27/06/2024	18.5	No Action Required – Continue Monitoring
28/06/2024	17	No Action Required – Continue Monitoring
29/06/2024	18.8	No Action Required – Continue Monitoring
30/06/2024	12.4	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note * - Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/07/2024	6.3	No Action Required – Continue Monitoring
2/07/2024	6.2	No Action Required – Continue Monitoring
3/07/2024	5.3	No Action Required – Continue Monitoring
4/07/2024	8.2	No Action Required – Continue Monitoring
5/07/2024	9	No Action Required – Continue Monitoring
6/07/2024	5.4	No Action Required – Continue Monitoring
7/07/2024	4.9	No Action Required – Continue Monitoring
8/07/2024	4	No Action Required – Continue Monitoring
9/07/2024	6.5	No Action Required – Continue Monitoring
10/07/2024	4.2	No Action Required – Continue Monitoring
11/07/2024	4.9	No Action Required – Continue Monitoring
12/07/2024	8.2	No Action Required – Continue Monitoring
13/07/2024	6.5	No Action Required – Continue Monitoring
14/07/2024	8.8	No Action Required – Continue Monitoring
15/07/2024	7.4	No Action Required – Continue Monitoring
16/07/2024	9	No Action Required – Continue Monitoring
17/07/2024	6.7	No Action Required – Continue Monitoring
18/07/2024	7.4	No Action Required – Continue Monitoring
19/07/2024	9.4	No Action Required – Continue Monitoring
20/07/2024	13.7	No Action Required – Continue Monitoring
21/07/2024	18.2	No Action Required – Continue Monitoring
22/07/2024	9.8	No Action Required – Continue Monitoring
23/07/2024	10.6	No Action Required – Continue Monitoring
24/07/2024	16.6	No Action Required – Continue Monitoring
25/07/2024	14.5	No Action Required – Continue Monitoring
26/07/2024	10.3	No Action Required – Continue Monitoring
27/07/2024	7.6	No Action Required – Continue Monitoring
28/07/2024	4.5	No Action Required – Continue Monitoring
29/07/2024	9.2	No Action Required – Continue Monitoring
30/07/2024	9.9	No Action Required – Continue Monitoring
31/07/2024	9.2	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/08/2024	9.31	No Action Required – Continue Monitoring
2/08/2024	9.62	No Action Required – Continue Monitoring
3/08/2024	10.7	No Action Required – Continue Monitoring
4/08/2024	12.8	No Action Required – Continue Monitoring
5/08/2024	13.3	No Action Required – Continue Monitoring
6/08/2024	7.07	No Action Required – Continue Monitoring
7/08/2024	7.34	No Action Required – Continue Monitoring
8/08/2024	10.2	No Action Required – Continue Monitoring
9/08/2024	11.5	No Action Required – Continue Monitoring
10/08/2024	15	No Action Required – Continue Monitoring
11/08/2024	15.3	No Action Required – Continue Monitoring
12/08/2024	10.3	No Action Required – Continue Monitoring
13/08/2024	6.45	No Action Required – Continue Monitoring
14/08/2024	4.76	No Action Required – Continue Monitoring
15/08/2024	4.62	No Action Required – Continue Monitoring
16/08/2024	1.58	No Action Required – Continue Monitoring
17/08/2024	6.41	No Action Required – Continue Monitoring
18/08/2024	8.72	No Action Required – Continue Monitoring
19/08/2024	8.77	No Action Required – Continue Monitoring
20/08/2024	13.6	No Action Required – Continue Monitoring
21/08/2024	23.8	No Action Required – Continue Monitoring
22/08/2024	25.2	No Action Required – Continue Monitoring
23/08/2024	15.2	No Action Required – Continue Monitoring
24/08/2024	16.3	No Action Required – Continue Monitoring
25/08/2024	20.9	No Action Required – Continue Monitoring
26/08/2024	25.4	No Action Required – Continue Monitoring
27/08/2024	23.7	No Action Required – Continue Monitoring
28/08/2024	27	No Action Required – Continue Monitoring
29/08/2024	29.9	No Action Required – Continue Monitoring
30/08/2024	31.1	No Action Required – Continue Monitoring
31/08/2024	49.9	Actioned According to Management Plans

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/09/2024	25.9	No Action Required – Continue Monitoring
2/09/2024	21.9	No Action Required – Continue Monitoring
3/09/2024	22.4	No Action Required – Continue Monitoring
4/09/2024	22.1	No Action Required – Continue Monitoring
5/09/2024	28.2	No Action Required – Continue Monitoring
6/09/2024	23.4	No Action Required – Continue Monitoring
7/09/2024	24.6	No Action Required – Continue Monitoring
8/09/2024	21.3	No Action Required – Continue Monitoring
9/09/2024	14	No Action Required – Continue Monitoring
10/09/2024	17.5	No Action Required – Continue Monitoring
11/09/2024	27.3	No Action Required – Continue Monitoring
12/09/2024	18.9	No Action Required – Continue Monitoring
13/09/2024	7.38	No Action Required – Continue Monitoring
14/09/2024	6.52	No Action Required – Continue Monitoring
15/09/2024	8.4	No Action Required – Continue Monitoring
16/09/2024	11	No Action Required – Continue Monitoring
17/09/2024	14.4	No Action Required – Continue Monitoring
18/09/2024	19.1	No Action Required – Continue Monitoring
19/09/2024	20.3	No Action Required – Continue Monitoring
20/09/2024	20.5	No Action Required – Continue Monitoring
21/09/2024	16.3	No Action Required – Continue Monitoring
22/09/2024	14.7	No Action Required – Continue Monitoring
23/09/2024	17.4	No Action Required – Continue Monitoring
24/09/2024	17.4	No Action Required – Continue Monitoring
25/09/2024	26	No Action Required – Continue Monitoring
26/09/2024	30.3	No Action Required – Continue Monitoring
27/09/2024	8.03	No Action Required – Continue Monitoring
28/09/2024	5.75	No Action Required – Continue Monitoring
29/09/2024	6.47	No Action Required – Continue Monitoring
30/09/2024	9.4	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/10/2024	12.5	No Action Required – Continue Monitoring
2/10/2024	16.6	No Action Required – Continue Monitoring
3/10/2024	21	No Action Required – Continue Monitoring
4/10/2024	19.2	No Action Required – Continue Monitoring
5/10/2024	18.6	No Action Required – Continue Monitoring
6/10/2024	12.5	No Action Required – Continue Monitoring
7/10/2024	12.7	No Action Required – Continue Monitoring
8/10/2024	17.2	No Action Required – Continue Monitoring
9/10/2024	(S)	No Action Required – Continue Monitoring
10/10/2024	(S)	No Action Required – Continue Monitoring
11/10/2024	24.4	No Action Required – Continue Monitoring
12/10/2024	26.9	No Action Required – Continue Monitoring
13/10/2024	18.2	No Action Required – Continue Monitoring
14/10/2024	14.2	No Action Required – Continue Monitoring
15/10/2024	9.66	No Action Required – Continue Monitoring
16/10/2024	12	No Action Required – Continue Monitoring
17/10/2024	13.9	No Action Required – Continue Monitoring
18/10/2024	18.2	No Action Required – Continue Monitoring
19/10/2024	21	No Action Required – Continue Monitoring
20/10/2024	8.98	No Action Required – Continue Monitoring
21/10/2024	15.2	No Action Required – Continue Monitoring
22/10/2024	21.7	No Action Required – Continue Monitoring
23/10/2024	22.1	No Action Required – Continue Monitoring
24/10/2024	31	No Action Required – Continue Monitoring
25/10/2024	18	No Action Required – Continue Monitoring
26/10/2024	16.5	No Action Required – Continue Monitoring
27/10/2024	19.5	No Action Required – Continue Monitoring
28/10/2024	26.1	No Action Required – Continue Monitoring
29/10/2024	31	No Action Required – Continue Monitoring
30/10/2024	26.9	No Action Required – Continue Monitoring
31/10/2024	30.1	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/11/2024	27.1	No Action Required – Continue Monitoring
2/11/2024	21.3	No Action Required – Continue Monitoring
3/11/2024	20.4	No Mining Activities
4/11/2024	30.3	No Action Required – Continue Monitoring
5/11/2024	36.1	No Action Required – Continue Monitoring
6/11/2024	27.1	No Action Required – Continue Monitoring
7/11/2024	43.6	No Action Required – Continue Monitoring
8/11/2024	31.6	No Action Required – Continue Monitoring
9/11/2024	30.4	No Action Required – Continue Monitoring
10/11/2024	52.3	No Mining Activities
11/11/2024	38	No Action Required – Continue Monitoring
12/11/2024	20.4	No Action Required – Continue Monitoring
13/11/2024	13.5	No Action Required – Continue Monitoring
14/11/2024	14.6	No Action Required – Continue Monitoring
15/11/2024	17.3	No Action Required – Continue Monitoring
16/11/2024	12.3	No Action Required – Continue Monitoring
17/11/2024	9.81	No Mining Activities
18/11/2024	13.4	No Action Required – Continue Monitoring
19/11/2024	11.6	No Action Required – Continue Monitoring
20/11/2024	9.01	No Action Required – Continue Monitoring
21/11/2024	9.46	No Action Required – Continue Monitoring
22/11/2024	13.2	No Action Required – Continue Monitoring
23/11/2024	12.9	No Action Required – Continue Monitoring
24/11/2024	20.6	No Mining Activities
25/11/2024	31.4	No Action Required – Continue Monitoring
26/11/2024	28.5	No Action Required – Continue Monitoring
27/11/2024	25.8	No Action Required – Continue Monitoring
28/11/2024	24.6	No Action Required – Continue Monitoring
29/11/2024	12.9	No Action Required – Continue Monitoring
30/11/2024	7.04	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/12/2024	5.56	No Action Required – Continue Monitoring
2/12/2024	1.5	No Action Required – Continue Monitoring
3/12/2024	15.1	No Action Required – Continue Monitoring
4/12/2024	6.68	No Action Required – Continue Monitoring
5/12/2024	4.76	No Action Required – Continue Monitoring
6/12/2024	6.17	No Action Required – Continue Monitoring
7/12/2024	5.48	No Action Required – Continue Monitoring
8/12/2024	5.83	No Action Required – Continue Monitoring
9/12/2024	5.11	No Action Required – Continue Monitoring
10/12/2024	(S)	No Action Required – Continue Monitoring
11/12/2024	(S)	No Action Required – Continue Monitoring
12/12/2024	15.4	No Action Required – Continue Monitoring
13/12/2024	14.3	No Action Required – Continue Monitoring
14/12/2024	7.96	No Action Required – Continue Monitoring
15/12/2024	5.99	No Action Required – Continue Monitoring
16/12/2024	5.7	No Action Required – Continue Monitoring
17/12/2024	3.91	No Action Required – Continue Monitoring
18/12/2024	2.96	No Action Required – Continue Monitoring
19/12/2024	(S)	No Action Required – Continue Monitoring
20/12/2024	(S)	No Action Required – Continue Monitoring
21/12/2024	12.8	No Action Required – Continue Monitoring
22/12/2024	13.2	No Action Required – Continue Monitoring
23/12/2024	13.5	No Action Required – Continue Monitoring
24/12/2024	10.4	No Action Required – Continue Monitoring
25/12/2024	8.83	No Action Required – Continue Monitoring
26/12/2024	8.4	No Action Required – Continue Monitoring
27/12/2024	(S)	No Action Required – Continue Monitoring
28/12/2024	(S)	No Action Required – Continue Monitoring
29/12/2024	(S)	No Action Required – Continue Monitoring
30/12/2024	10.8	No Action Required – Continue Monitoring
31/12/2024	11.9	No Action Required – Continue Monitoring

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*