




Vickery Site Monitoring



PM_{2.5}: particle matter 2.5 micron or less in size.
 (C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
 * N/A: Data Not available due to servicing, power outage or communication issue.



PM₁₀: particle matter 10 micron or less in size.
(C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
* N/A: Data Not available due to servicing, power outage or communication issue.



PM_{2.5}: particle matter 2.5 micron or less in size.
 (C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
 * N/A: Data Not available due to servicing, power outage or communication issue.



5 Braymont Rd Gunnedah, NSW 2380



PM₁₀: particle matter 10 micron or less in size.
 (C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
 * N/A: Data Not available due to servicing, power outage or communication issue.

The real time noise monitor is used as operational management tool (no criteria apply)


Noise (LF) ²³		
Average reading for the period of 26 June 2024		
Day: 7am-6pm 37.1 dB(A)	Evening 6pm-10pm 25.4 dB(A)	Nights 10pm-7am 26.3 dB(A)
Operational Response:		
No Action Required - Continue Monitoring		

5. LF is estimated equivalent mining noise (LF = low frequency for band 20-630 HZ); Monitoring results may include noise from other sources.

*Elevated levels affected by non- related mining event.

N/A: Data Not available due to servicing, power outage or communication issue.

(C): recalculation of the average as some data unavailable due to rain, power or communications.



For further information contact:

0457 464 129 or VickeryEnvironment@whitehavencoal.com.au