

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/07/2017	4.99	5.45	No action required
2/07/2017	4.62	4.29	No action required
3/07/2017	4.98	4.64	No action required
4/07/2017	2.61	2.51	No action required
5/07/2017	2.55	2.54	No action required
6/07/2017	2.43	2.53	No action required
7/07/2017	3.68	3.41	No action required
8/07/2017	3.34	3.25	No action required
9/07/2017	4.07	3.53	No action required
10/07/2017	5.06	13.14	No action required
11/07/2017	4.61	9.10	No action required
12/07/2017	5.00	14.38	No action required
13/07/2017	4.69	5.40	No action required
14/07/2017	5.71	7.83	No action required
15/07/2017	3.96	2.52	No action required
16/07/2017	2.51	1.52	No action required
17/07/2017	2.23	3.12	No action required
18/07/2017	2.82	2.19	No action required
19/07/2017	3.55	2.88	No action required
20/07/2017	1.72	1.46	No action required
21/07/2017	6.43	6.95	No action required
22/07/2017	4.09	2.41	No action required
23/07/2017	3.99	2.80	No action required
24/07/2017	3.72	5.11	No action required
25/07/2017	5.46	4.91	No action required
26/07/2017	5.64	9.63	No action required
27/07/2017	5.82	15.16	No action required
28/07/2017	7.29	9.47	No action required
29/07/2017	7.84	9.00	No action required
30/07/2017	9.17	13.01	No action required
31/07/2017	No Data	No Data	Insufficient data to determine average; due to planned power outage beyond the control of MCCM

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/08/2017	5.4	10.1	No action required
2/08/2017	9.1	11.9	No action required
3/08/2017	10.5	9.9	No action required
4/08/2017	0.8	0.8	No action required
5/08/2017	1.7	1.2	No action required
6/08/2017	2.8	1.4	No action required
7/08/2017	3.1	2.8	No action required
8/08/2017	3.4	1.9	No action required
9/08/2017	4.2	5.7	No action required
10/08/2017	3.3	5.6	No action required
11/08/2017	10.1	13.3	No action required
12/08/2017	7.4	12.7	No action required
13/08/2017	5.8	9.9	No action required
14/08/2017	9.3	10.7	No action required
15/08/2017	10.3	10.4	No action required
16/08/2017	11.6	14.7	No action required
17/08/2017	8.7	11.4	No action required
18/08/2017	8.8	10.3	No action required
19/08/2017	5.8	2.9	No action required
20/08/2017	7.7	8.7	No action required
21/08/2017	17.7	20.3	No action required
22/08/2017	17.1	14.9	No action required
23/08/2017	13.5	15.9	No action required
24/08/2017	9.6	11.2	No action required
25/08/2017	7.9	14.0	No action required
26/08/2017	9.2	14.1	No action required
27/08/2017	8.8	6.9	No action required
28/08/2017	7.5	9.8	No action required
29/08/2017	11.1	12.8	No action required
30/08/2017	9.7	13.1	No action required
31/08/2017	14.4	24.8	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/09/2017	14.3	17.8	No action required
2/09/2017	7.9	11.4	No action required
3/09/2017	16.0	16.1	No action required
4/09/2017	12.1	19.3	No action required
5/09/2017	9.4	13.5	No action required
6/09/2017	7.6	7.9	No action required
7/09/2017	5.7	8.8	No action required
8/09/2017	14.5	7.3	No action required
9/09/2017	16.5	9.2	No action required
10/09/2017	10.5	19.8	No action required
11/09/2017	8.0	8.7	No action required
12/09/2017	8.3	10.5	No action required
13/09/2017	17.3	17.5	No action required
14/09/2017	7.7	3.9	No action required
15/09/2017	6.1	3.5	No action required
16/09/2017	6.5	3.5	No action required
17/09/2017	7.9	6.8	No action required
18/09/2017	9.8	7.9	No action required
19/09/2017	14.1	16.5	No action required
20/09/2017	12.6	11.5	No action required
21/09/2017	9.7	14.3	No action required
22/09/2017	14.8	14.5	No action required
23/09/2017	23.8	20.6	No action required
24/09/2017	28.2	23.2	No action required
25/09/2017	19.8	16.1	No action required
26/09/2017	17.2	22.8	No action required
27/09/2017	24.3	29.6	No action required
28/09/2017	25.1	21.7	No action required
29/09/2017	5.7	6.0	No action required
30/09/2017	5.8	4.0	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/10/2017	16.4	11.6	No action required
2/10/2017	3.7	5.0	No action required
3/10/2017	4.7	4.1	No action required
4/10/2017	4.7	2.6	No action required
5/10/2017	7.4	5.5	No action required
6/10/2017	24.9	12.7	No action required
7/10/2017	13.8	21.1	No action required
8/10/2017	12.3	11.4	No action required
9/10/2017	7.1	8.8	No action required
10/10/2017	8.6	10.0	No action required
11/10/2017	13.6	12.3	No action required
12/10/2017	6.7	5.4	No action required
13/10/2017	6.6	2.9	No action required
14/10/2017	6.4	6.5	No action required
15/10/2017	6.5	7.9	No action required
16/10/2017	no data	8.0	No action required - power outage at TEOM 1.
17/10/2017	4.9	no data	No action required - power outage at TEOM 2.
18/10/2017	5.5	4.0	No action required
19/10/2017	8.7	9.2	No action required
20/10/2017	6.4	6.3	No action required
21/10/2017	4.9	5.5	No action required
22/10/2017	8.3	4.3	No action required
23/10/2017	6.7	5.6	No action required
24/10/2017	5.5	2.8	No action required
25/10/2017	no data	no data	No action required - maintenance and recalibration undertaken.
26/10/2017	20.8	24.7	No action required
27/10/2017	15.3	11.3	No action required
28/10/2017	6.6	7.2	No action required
29/10/2017	9.8	12.4	No action required
30/10/2017	12.1	15.0	No action required
31/10/2017	6.6	5.5	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/11/2017	6.1	8.2	No action required
2/11/2017	8.6	10.8	No action required
3/11/2017	13.1	14.9	No action required
4/11/2017	13.4	16.3	No action required
5/11/2017	13.0	21.4	No action required
6/11/2017	insufficient data	Insufficient data	No action required - power outage at TEOM 1 & TEOM2
7/11/2017	5.6	7.0	No action required
8/11/2017	6.1	14.3	No action required
9/11/2017	5.1	16.1	No action required
10/11/2017	9.2	13.9	No action required
11/11/2017	6.0	11.4	No action required
12/11/2017	8.9	13.2	No action required
13/11/2017	12.5	13.7	No action required
14/11/2017	11.8	12.0	No action required
15/11/2017	10.9	11.1	No action required
16/11/2017	6.5	11.8	No action required
17/11/2017	7.5	11.6	No action required
18/11/2017	2.5	9.8	No action required
19/11/2017	4.1	12.0	No action required
20/11/2017	3.5	8.8	No action required
21/11/2017	4.4	9.0	No action required
22/11/2017	5.9	9.9	No action required
23/11/2017	4.3	5.4	No action required
24/11/2017	6.1	6.2	No action required
25/11/2017	11.7	11.2	No action required
26/11/2017	10.3	11.5	No action required
27/11/2017	9.9	20.0	No action required
28/11/2017	10.2	10.1	No action required
29/11/2017	8.7	8.0	No action required
30/11/2017	3.4	1.8	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/12/2017	2.7	10.1	No action required
2/12/2017	4.5	11.9	No action required
3/12/2017	1.8	6.8	No action required
4/12/2017	4.0	7.5	No action required
5/12/2017	6.5	6.0	No action required
6/12/2017	5.2	5.4	No action required
7/12/2017	6.5	7.6	No action required
8/12/2017	11.9	17.1	No action required
9/12/2017	13.5	16.4	No action required
10/12/2017	8.9	24.5	No action required
11/12/2017	13.2	24.1	No action required
12/12/2017	12.0	16.8	No action required
13/12/2017	14.6	17.5	No action required
14/12/2017	15.8	23.1	No action required
15/12/2017	16.4	30.5	No action required
16/12/2017	17.5	20.2	No action required
17/12/2017	12.8	7.2	No action required
18/12/2017	14.0	17.7	No action required
19/12/2017	12.9	13.4	No action required
20/12/2017	17.5	18.1	No action required
21/12/2017	13.6	20.1	No action required
22/12/2017	9.4	16.3	No action required
23/12/2017	10.8	24.6	No action required
24/12/2017	12.3	13.9	No action required
25/12/2017	11.7	12.9	No action required
26/12/2017	13.3	14.5	No action required
27/12/2017	4.8	5.4	No action required
28/12/2017	8.4	12.1	No action required
29/12/2017	8.3	6.7	No action required
30/12/2017	9.2	15.9	No action required
31/12/2017	9.3	13.8	No action required

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy