

## Narrabri Coal Operations Pty Ltd 2010 Complaints Register

Method	Date/Time of Complaint	Nature of Complaint	Investigation	Action Taken / Follow- up
Complaint to Project Manager	9/02/2010 7:15am	Screeching noise coming from mine site between 6am and 7am	Advised complainant that matter would be investigated to attempt to identify the noise source. Subsequent discussion between staff identified that no surface activities (including drilling) that could be creating such a noise were operating at that time	No further action required
Phone call to General Manager	9/09/2010 3:30pm	Noise from the mine site	•	Real time noise monitor used at property