

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/9/2025	10	
2/9/2025	15.2	
3/9/2025	15.1	
4/9/2025	12.5	
5/9/2025	17.3	
6/9/2025	19.6	
7/9/2025	16.2	
8/9/2025	15.2	
9/9/2025	17	
10/9/2025	10.9	
11/9/2025	6.19	
12/9/2025	5.74	
13/9/2025	10.3	
14/9/2025	18.2	
15/9/2025	14.5	
16/9/2025	14.8	
17/9/2025	19	
18/9/2025	13.4	
19/9/2025	19.3	
20/9/2025	16.7	
21/9/2025	6.41	
22/9/2025	9.83	
23/9/2025	11.5	
24/9/2025	10.4	
25/9/2025	14.8	
26/9/2025	17.4	
27/9/2025	20.8	
28/9/2025	27.3	
29/9/2025	22.5	
30/9/2025	20.9	

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.