

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/04/2020	13.6	No action required
2/04/2020	13.5	No action required
3/04/2020	8.5	No action required
4/04/2020	20.8	No action required
5/04/2020	21.6	No Mining Activity
6/04/2020	15.1	No action required
7/04/2020	15.9	No action required
8/04/2020	9.5(C)	No action required
9/04/2020	10.8	No action required
10/04/2020	6.4	No action required
11/04/2020	13.5	No action required
12/04/2020	38.1	No Mining Activity
13/04/2020	17.3	No action required
14/04/2020	21.7	No action required
15/04/2020	20.5	No action required
16/04/2020	19.5	No action required
17/04/2020	20.2	No action required
18/04/2020	13.1	No action required
19/04/2020	13.7	No Mining Activity
20/04/2020	14.8	No action required
21/04/2020	21	No action required
22/04/2020	16.9	No action required
23/04/2020	18.4	No action required
24/04/2020	21	No action required
25/04/2020	24.5	No action required
26/04/2020	26.3	No Mining Activity
27/04/2020	35.6	No action required
28/04/2020	17.9	No action required
29/04/2020	11.9	No action required
30/04/2020	12.7	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*