

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/03/2021	14.4	No action required
2/03/2021	21.7	No action required
3/03/2021	20.1	No action required
4/03/2021	12.5	No action required
5/03/2021	17.2	No action required
6/03/2021	19.7	No action required
7/03/2021	17.1	No Mining Activities
8/03/2021	16.3	No action required
9/03/2021	8.9 (C)	No action required
10/03/2021	11.1	No action required
11/03/2021	11.0 (C)	No action required
12/03/2021	9.1 (C)	No action required
13/03/2021	10.4	No action required
14/03/2021	9	No Mining Activities
15/03/2021	6.4	No action required
16/03/2021	8.9	No action required
17/03/2021	5.6 (C)	No action required
18/03/2021	5.9	No action required
19/03/2021	6.3	No action required
20/03/2021	8.8	No action required
21/03/2021	7.8	No Mining Activities
22/03/2021	4.6	No action required
23/03/2021	9.6	No action required
24/03/2021	11.6	No action required
25/03/2021	16	No action required
26/03/2021	13.9	No action required
27/03/2021	14.1	No action required
28/03/2021	10.8	No Mining Activities
29/03/2021	17.4	No action required
30/03/2021	13.6	No action required
31/03/2021	12.7	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*