

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [$\mu\text{g}/\text{m}^3$]	Operational Response
1/04/2021	12.1	No action required
2/04/2021	12.2	No action required
3/04/2021	13.6	No action required
4/04/2021	9.0	No Mining Activities
5/04/2021	14.6	No action required
6/04/2021	17.1	No action required
7/04/2021	12.0	No action required
8/04/2021	11.0	No action required
9/04/2021	22.9	No action required
10/04/2021	26.8	No action required
11/04/2021	20.4	No Mining Activities
12/04/2021	16.4	No action required
13/04/2021	26.4	No action required
14/04/2021	29.4	No action required
15/04/2021	36.2	No action required
16/04/2021	27.2	No action required
17/04/2021	10.8	No action required
18/04/2021	4.4	No Mining Activities
19/04/2021	8.9	No action required
20/04/2021	17.7	No action required
21/04/2021	16.7	No action required
22/04/2021	15.3	No action required
23/04/2021	20.4	No action required
24/04/2021	22.9	No action required
25/04/2021	20.6	No Mining Activities
26/04/2021	30.7	No action required
27/04/2021	26.2	No action required
28/04/2021	58.3	No action required
29/04/2021	29.3	No action required
30/04/2021	25.6	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.*