

**BTM Air Quality Management Strategy
Tarrawonga Coal Mine
Dust Monitoring**

Date	Flixton* PM ₁₀ 24hr Average [µg/m ³]	Operational Response
01-03-23	33.4 (C)	No action required
02-03-23	27	No action required
03-03-23	17.4	No action required
04-03-23	18.8	No action required
05-03-23	24.2	No Mining Activities
06-03-23	36	No action required
07-03-23	39.5	No action required
08-03-23	36.9	No action required
09-03-23	21.7	No action required
10-03-23	36.1	No action required
11-03-23	22.1	No action required
12-03-23	5.5	No Mining Activities
13-03-23	11.9 (C)	No action required
14-03-23	7.2 (C)	No action required
15-03-23	11.9	No action required
16-03-23	16.1	No action required
17-03-23	20.1	No action required
18-03-23	15.4	No action required
19-03-23	18.6	No Mining Activities
20-03-23	26.1	No action required
21-03-23	Power outage	No action required
22-03-23	12	No action required
23-03-23	15.8	No action required
24-03-23	Power outage	No action required
25-03-23	Power outage	No action required
26-03-23	9.3	No Mining Activities
27-03-23	Power outage	No action required
28-03-23	12.3	No action required
29-03-23	8.9	No action required
30-03-23	9.5	No action required
31-03-23	10.3	No action required

(C) – Result recalculated from one hour average due to incomplete data.

S -- Servicing / calibration/ comms problem of unit- no data available

N/A – TEOM Power Outage due to high rainfall.

*Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy Therefore No Limits Apply.*

Note 2: Data from the 1st to the 20th of December 2021 was downloaded from the TEOM after repairs to communications were completed.