

Date	TEOM1 PM10 24hr Average	TEOM2 PM10 24hr Average	Operational Response
1/01/2018	9.3	11.4	No action required
2/01/2018	10.8	14.1	No action required
3/01/2018	14.0	22.1	No action required
4/01/2018	12.2	19.4	No action required
5/01/2018	15.4	11.7	No action required
6/01/2018	13.8	15.0	No action required
7/01/2018	16.2	23.4	No action required
8/01/2018	20.2	23.9	No action required
9/01/2018	23.0	22.5	No action required
10/01/2018	N/A	N/A	No action required - power outage at TEOM 1 & TEOM 2
11/01/2018	12.5	9.5	No action required
12/01/2018	12.7	11.7	No action required
13/01/2018	22.7	21.9	No action required
14/01/2018	7.9	9.3	No action required
15/01/2018	7.4	14.1	No action required
16/01/2018	15.1	25.7	No action required
17/01/2018	16.8	29.2	No action required
18/01/2018	20.2	36.4	No action required
19/01/2018	20.2	24.7	No action required
20/01/2018	18.1	23.2	No action required
21/01/2018	17.8	32.1	No action required
22/01/2018	N/A	25.6	No action required - power outage at TEOM 1
23/01/2018	N/A	37.6	No action required - maintenance and callibrations undertaken at TEOM 1
24/01/2018	N/A	28.3	No action required - mechanical error at TEOM 1
25/01/2018	N/A	27.6	No action required - mechanical error at TEOM 1
26/01/2018	N/A	18.7	No action required - mechanical error at TEOM 1
27/01/2018	N/A	10.9	No action required - mechanical error at TEOM 1
28/01/2018	N/A	N/A	No action required - mechanical error at TEOM 1 & power outage at TEOM 2
29/01/2018	N/A	N/A	No action required - mechanical error at TEOM 1 & power outage at TEOM 2
30/01/2018	N/A	N/A	No action required - mechanical error at TEOM 1 & power outage at TEOM 2
31/01/2018	22.9	N/A	No action required - power outage at TEOM 2

Note - TEOM1 and TEOM2 are utilised as management units in accordance with the approved BTM Air Quality Management Strategy  
N/A - not available