



Tarrawonga Site Monitoring

These monitors are used as operation management tools (no criteria apply)

 Air Quality (PM ₁₀)
Average reading for 24hr period 00:00 – 23:59 hrs on 22 October 2020
NA µg/m³
Operational Response: Power outage at monitor due to rain, data invalid - Continue Monitoring


1. PM₁₀: particle matter 10 micron or less in size.

 Noise (LF) ²			
Average reading for the period of 22 October 2020			
Day: 7am-6pm	Evening 6pm-10pm	Nights 10pm-7am	
28.5 dB(A)	20.6 dB(A)	27.8 dB(A)	
Operational Response:			
No Action Required – Continue Monitoring			

2. LF is estimated equivalent mining noise (LF = low frequency for band 20-630 HZ); Monitoring results may include noise from other sources.

*Elevated levels affected by non-related mining event.

N/A: Data Not available due to servicing, power outage or communication issue.

 Weather
Weather condition and forecast is available at: http://www.whitehavencoal.com.au/weather/
Operational Response: No Action Required– Continue Monitoring

For further information contact:

02 6741 5009 or TarrawongaEnvironment@whitehavencoal.com.au