



Vickery Site Monitoring

These monitors are used as operation management tools (no criteria apply)



PM_{2.5}: particle matter 2.5 micron or less in size.
(C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
* N/A: Data Not available due to servicing, power outage or communication issue.



PM₁₀: particle matter 10 micron or less in size.
(C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
* N/A: Data Not available due to servicing, power outage or communication issue.




PM_{2.5}: particle matter 2.5 micron or less in size.
(C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
* N/A: Data Not available due to servicing, power outage or communication issue.



5 Braymont Rd Gunnedah, NSW 2380



PM₁₀: particle matter 10 micron or less in size.
(C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.
* N/A: Data Not available due to servicing, power outage or communication issue.



- 5. LF is estimated equivalent mining noise (LF = low frequency for band 20-630 HZ); Monitoring results may include noise from other sources.
 - *Elevated levels affected by non- related mining event.
 - N/A: Data Not available due to servicing, power outage or communication issue.
 - (C): recalculation of the average as some data unavailable due to rain, power or communications.



For further information contact:

0457 464 129 or VickeryEnvironment@whitehavencoal.com.au