

**TARRAWONGA COAL MINE**  
**Dust Monitoring**

Date	Flixton* PM <sub>10</sub> 24hr Average [ $\mu\text{g}/\text{m}^3$ ]	Operational Response
1/1/2019	53.8	Actioned and Monitored operation according to Management Plan
1/2/2019	14.2	No action required
1/3/2019	33.4	No action required
1/4/2019	27.8	No action required
1/5/2019	22.7	No action required
1/6/2019	32.4	No action required
1/7/2019	26.4	No action required
1/8/2019	15.4	No action required
1/9/2019	26.8	No action required
1/10/2019	32.8	Actioned and Monitored operation according to Management Plan
1/11/2019	15.8	No action required
1/12/2019	19.4	No action required
1/13/2019	17.0	No action required
1/14/2019	23.0	Actioned and Monitored operation according to Management Plan
1/15/2019	41.6	Actioned and Monitored operation according to Management Plan
1/16/2019	52.4	Actioned and Monitored operation according to Management Plan
1/17/2019	44.1	No action required
1/18/2019	33.8	No action required
1/19/2019	63.3	Actioned and Monitored operation according to Management Plan
1/20/2019	25.0	No action required
1/21/2019	16.1	No action required
1/22/2019	19.8	No action required
1/23/2019	19.6	No action required
1/24/2019	27.6	No action required
1/25/2019	21.5	No action required
1/26/2019	23.2	No action required
1/27/2019	23.5	No action required
1/28/2019	38.8	No action required
1/29/2019	37.5	No action required
1/30/2019	29.8	No action required
1/31/2019	27.7	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

Note \*- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.