

**TARRAWONGA COAL MINE**  
**Dust Monitor part of the BTM network**

Date	Flixton* PM <sub>10</sub> 24hr Average [µg/m <sup>3</sup> ]	Operational Response
1/04/2019	22.3	No action required
2/04/2019	15.3	No action required
3/04/2019	12.5	No action required
4/04/2019	14.8	No action required
5/04/2019	16.2	No action required
6/04/2019	15.9	No action required
7/04/2019	26.6	No action required
8/04/2019	46.3	Actioned and Monitored operation according to Management Plan
9/04/2019	61.5	Actioned and Monitored operation according to Management Plan
10/04/2019	34.1	No action required
11/04/2019	24.1	No action required
12/04/2019	25.3	No action required
13/04/2019	20.7	No action required
14/04/2019	29.0	No action required
15/04/2019	24.6	No action required
16/04/2019	30.1	No action required
17/04/2019	23.9	No action required
18/04/2019	36.6	No action required
19/04/2019	19.1	No action required
20/04/2019	12.8	No action required
21/04/2019	26.6	No action required
22/04/2019	26.1	No action required
23/04/2019	19.2	No action required
24/04/2019	30.2	No action required
25/04/2019	43.6	Actioned and Monitored operation according to Management Plan
26/04/2019	58.0	Actioned and Monitored operation according to Management Plan
27/04/2019	47.3	Actioned and Monitored operation according to Management Plan
28/04/2019	50.4	Actioned and Monitored operation according to Management Plan
29/04/2019	S	No action required
30/04/2019	31.9	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

Note \*- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.