

**TARRAWONGA COAL MINE**  
**Dust Monitor part of the BTM network**

Date	Flixton* PM <sub>10</sub> 24hr Average [µg/m <sup>3</sup> ]	Operational Response
1/05/2019	13.1	No action required
2/05/2019	33.5	No action required
3/05/2019	17.0	No action required
4/05/2019	4.8	No action required
5/05/2019	6.3	No action required
6/05/2019	7.5	No action required
7/05/2019	10.2	No action required
8/05/2019	17.7	No action required
9/05/2019	23.5	No action required
10/05/2019	26.2	No action required
11/05/2019	12.0	No action required
12/05/2019	14.3	No action required
13/05/2019	23.8	No action required
14/05/2019	36.5	No action required
15/05/2019	51.0	Actioned and Monitored operation according to Management Plan
16/05/2019	42.5	Actioned and Monitored operation according to Management Plan
17/05/2019	21.5	No action required
18/05/2019	28.9	No action required
19/05/2019	25.6	No action required
20/05/2019	32.8	No action required
21/05/2019	32.5	No action required
22/05/2019	32.5	No action required
23/05/2019	49.3	Actioned and Monitored operation according to Management Plan
24/05/2019	33.5	No action required
25/05/2019	31.9	No action required
26/05/2019	21.5	No action required
27/05/2019	26.7	No action required
28/05/2019	31.9	No action required
29/05/2019	32.9	No action required
30/05/2019	12.4	No action required
31/05/2019	16.5	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

Note \*- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.