

TARRAWONGA COAL MINE
Dust Monitor part of the BTM network

Date	Flixton* PM ₁₀ 24hr Average [µg/m ³]	Operational Response
1/06/2019	29.0	No action required
2/06/2019	15.8	No action required
3/06/2019	7.5	No action required
4/06/2019	6.4	No action required
5/06/2019	12.8	No action required
6/06/2019	13.3	No action required
7/06/2019	16.3	No action required
8/06/2019	9.3	No action required
9/06/2019	3.3	No action required
10/06/2019	15.3	No action required
11/06/2019	11.9	No action required
12/06/2019	19.6	No action required
13/06/2019	19.5	No action required
14/06/2019	8.1	No action required
15/06/2019	14.2	No action required
16/06/2019	20.4	No action required
17/06/2019	18.3	No action required
18/06/2019	30.3	No action required
19/06/2019	17.2	No action required
20/06/2019	26.4	No action required
21/06/2019	16.0	No action required
22/06/2019	17.1	No action required
23/06/2019	13.8	No action required
24/06/2019	17.3	No action required
25/06/2019	38.3	No action required
26/06/2019	25.2	No action required
27/06/2019	12.7	No action required
28/06/2019	17.8	No action required
29/06/2019	21.9	No action required
30/06/2019	36.8	No action required

(C) – Result calculated from incomplete data provided at least 75% of the data is successfully obtained.

S -- Servicing / calibration/ comms problem of unit- no data available

Note *- Flixton monitor is utilized as an operation management unit in accordance with the approved BTM Air Quality Management Strategy therefore No Limits Apply.

BTM: Boggabri, Tarrawonga, Maules' creek complex