Tarrawonga Coal Mine
469 Goonbri Road
Boggabri, NSW 2382

Tarrawonga Site Monitoring

These monitors are used as operation management tools (no criteria apply)

Air Quality (PM_{10})
Average reading for 24hr period 00:00 – 23:59 hrs on 19 October 2020
11.4 µg/m^3
Operational Response:
No Action Required - Continue Monitoring

1. *PM_{10}: particle matter 10 micron or less in size.*

Noise (LF)[2]		
Average reading for the period of 19 October 2020		
Day: 7am-6pm	Evening 6pm-10pm	Nights 10pm-7am
22.5 dB(A)	**18.9** dB(A)	**22.3** dB(A)
Operational Response:		
No Action Required – Continue Monitoring		

2. *LF is estimated equivalent mining noise (LF = low frequency for band 20-630 HZ); Monitoring results may include noise from other sources.*

**Elevated levels affected by non- related mining event.*
N/A: Data Not available due to servicing, power outage or communication issue.

Weather
Weather condition and forecast is available at: http://www.whitehavencoal.com.au/weather/
Operational Response:
No Action Required – Continue Monitoring

For further information contact:

02 6741 5009 or TarrawongaEnvironment@whitehavencoal.com.au